## Hi Rancher

# **FOX-Pro**



### **SPECIFICATIONS**

Display Big backlit FSTN LCD display and 5 inch LCD

Units kg/lb/ton/g/oz


Output 1\* USB 1\* RS232 1/2\*Bluetooth

A/D Resolution 24 bit

A/D Rate 120 times/second

Operating Temperature -10 °C - 40 °C

Size







### **EXCITATION**

Power

7.4v Li-ion Battery

#### **FEATURES**

Multi checkweigh function
 The screen backlight turns yellow
 and displays LO to indicate that it is below the lower limit.

The screen backlight turns blue and displays OK to indicate that the value is between the upper and lower limits.

The screen backlight turns red and displays HI to indicate that the value is above the upper limit.

 3\*output and 1\*input, Zero/Tare/Print can be operated by foot pedal

#### **FUNCTIONS**

- Animal weighing
- Checkweigh
- Data export to USB drive
- Grouping
- Calibration-free Operation
- Connecting to ear tag sticks to read EID
- Adding notes
- Connecting to AP