

HiRancher

# FOX



## SPECIFICATIONS

Display 1.35-inch 6-bit LCD display

Units kg / lb / ton / g / oz

Output 2\* RS232 / RS485

A/D Resolution 1,000,000

A/D Rate 10 times/second

Operating Temperature -10 °C - 40 °C

Size



## EXCITATION

Power	100-240V AC 6V3.2Ah Rechargeable Battery
Load cell	1-4*350Ω 1-8*700Ω
Analog Input Signal	±10mV

## FEATURES

- Rechargeable battery with 30hour life
- High contrast LCD display
- Rugged IP67 housing
- Manual and auto tare
- 12,000 records

## FUNCTIONS

- Animal weighing
- Checkweigh
- Positive/negative weighing
- Hold
- Weight Record