

HiRancher FOX

SPECIFICATIONS

Display	1.35-inch 6-bit LCD display
Units	kg / lb / ton / g / oz
Output	2* RS232 / RS485
A/D Resolution	1,000,000
A/D Rate	10 times/second
Operating Temperature	-10 °C - 40 °C



Size



EXCITATION

Power	100-240V AC 6V3.2Ah Rechargeable Battery
Load cell	1-4*350Ω 1-8*700Ω
Analog Input Signal	±10mV

FEATURES

- Rechargeable battery with 30hour life
- High contrast LCD display
- Rugged IP67 housing
- Manual and auto tare
- 12,000 records

FUNCTIONS

- Animal weighing
- Checkweigh
- Postive/negative weighing
- Hold
- Weight Record